

Switched Main Power

+

MAIN  
CONTACTOR

KILL-SW.

IGN-SW.


F 10A

FUSE

MOTOR TEMP

HEATSINK TEMP

TS



TRANSISTOR FAIL

Battery

BMS

B--

